

LABORATORY DETAIL REPORT

Client: *Inter-Source Recovery Systems, Inc.*

Date Reported : *08/30/07*

Project

Description : *Analysis of two solid samples (Job #51363).*

Sample ID : <u>"51363 Head, Dry after the wringer from the trailer"</u>						
Sampled By :			Date Received : <i>08/27/07</i>			
Sample Date :			Sample Type : <i>solid</i>			
Sample Time :						
Test	Result	Units of Measure	Method	Analyzed	Analyst	Comments
<i>Moisture</i>	<i>0.58</i>	<i>% by weight</i>	<i>EPA 160.3</i>	<i>08/27/07</i>		

Sample ID : <u>"51363 Block, Dry after the wringer from the trailer"</u>						
Sampled By :			Date Received : <i>08/27/07</i>			
Sample Date :			Sample Type : <i>solid</i>			
Sample Time :						
Test	Result	Units of Measure	Method	Analyzed	Analyst	Comments
<i>Moisture</i>	<i>0.96</i>	<i>% by weight</i>	<i>EPA 160.3</i>	<i>08/27/07</i>		